



# CITY OF HUNTINGTON BEACH

Finance Department  
Fiscal Services – Purchasing Division

Lori Ann Farrell  
Director of Finance

May 17, 2011

## QUESTION/ANSWER TO BID #11-0523 ROTARY AUTOMOTIVE LIFTS

1) Can you confirm the thickness of the existing concrete slab to ensure that is adequate for the lift anchorage? Answer: All the lift sites were test drilled to five (5) inches. The floor its self is over ten (10) inches.

Sharon Griffin/Buyer  
714/960-8878